











This instruction sheet covers the removal of the cable packing sock for IFC assemblies.






1	<p><b><u>Cable packaged in a box</u></b></p> <p>Open box</p>	
<p><b>or</b></p>		
	<p><b><u>Cable on reel</u></b></p> <p>Cut cable ties to free socks from reel</p> <p>Skip to step 6</p>	
2	<p>If fiber count is 12 or less skip to step 6</p>	
3	<p>Open end box as shown</p>	

## Instruction Sheet

## Removal

4	Remove two cable ties that hold the cable to the box	
5	Remove clear protective tubing surrounding cable	
6	Remove cable tie(s) securing sock to cable	 
7	Slide sock off	

8	Remove clear protective tubing from around the cable	
9		
10	Cut and remove cable tie securing bag	

11	Slide off poly bag to access connectors		
12	Remove protective tubing from cable		
12	Remove foam bag protecting the connectors		
13	Remove tape securing connectors together		



**A Furukawa Company**

OFS reserves the right to make changes to the prices and products described in this document at any time.

This document is for informational purposes only and is not intended to modify or supplement any OFS specifications or warranties relating to any of its products or services

Copyright 2013 OFS FITEL, LLC