




1. Supplier OFS	Information		2. Product Change/ Recall Notice No.	2a. Include on www.ofsoptics.com	
10 Brigh	tWave Boulevard, Carrollton, GA Engineer:	30117	2015-0022-1 D	YES	
3. Issue Da	te of Change/Recall	4. System & Product Descri	ription	1	
Novembe	er 2, 2015	EZ-Bend® 4.8 mm and 3.0 mm Assemblies			
5. New Pro	duct ID	6. Old Product ID			
None		Attached List			
7. Associate None	7. Associated Products or Changes Affected None				
8. Drawing	No.	9. Product Change Classification			
A08AK1	A08AK1058 D				
10. Classific	10. Classification Substantiation				
Doesn't i	Doesn't impact fit or function. The form is only realized on single ended assemblies				
Change t	11. Reason(s) for Change/Recall Change the Blue Nylon 900 um buffer to a White PVC 900 um buffer so that the white buffer can be adhered to the wall in the InvisiLight® format				
12. Descript	12. Description of Change/Recall				
Change t	Change the Blue Nylon 900 um buffer to a White PVC 900 um buffer				
13. Effect of	13. Effect of Change/Recall				
No know	No known effect				
14. Material	14. Material\Product Affected				
4.8 mm a	4.8 mm and 3.0 mm EZ-Bend Cordage				
15. Documen	15. Documentation Affected				
Drawing changed to allow the Premise cable codes with a white PVC 900 um buffer					
16. Supplier	Implementation Date	17. Modification Complet	ion Date		
Decembe	r 2, 2015	June 2, 2016			
18. Modifica	8. Modification/Recall Location				
Recall me	Recall modification not required				
19. Modification/Recall Cost					
NA					
20. Location and Quantity of Equipment NA					
21. Attachm	21. Attachments				
List of co	List of codes				
22. Commer Allows th	ats ne application of adhering the whit	te buffer to the wall with the I	nvisiLight Adhesive System	m	





Old Code
JR5DK001 XXXXXXXXXX
JR5DW001 XXXXXXXXXX
JR3DK001 XXXXXXXXXX
JR3DW001 XXXXXXXXXX
JRVDK001 XXXXXXXXXX
JRVDW001XXXXXXXXXX