



1.	1. Supplier Information		2. Product Change/ Recall Notice No.	2a. Include on www.ofsoptics.com	
	Manufactured in Carrollton and Contract Manufacturers		2007-0014-1 D	Yes	
3.	Issue Date of Change/Recall	4. System & Product Description			
	7/1/07	LT1B Splice Trays changes to foam insert			
5.	New Product ID	6. Old Product ID			
	N/A	All Codes remain the same			
7.	Associated Products or Changes Affected				
	None				
8.	Drawing No.	9. Product Change Classifi	cation		
	A04AK1054	D			
10.	Classification Substantiation				
	The change doesn't affect form, fit or function				
11.	. Reason(s) for Change/Recall				
	The foam insert can be either black or white				
12.	Description of Change/Recall				
	The foam insert that holds the fiber tubes in the slot has been changed to include black and white foam				
13.	Effect of Change/Recall				
	None				
14.	Material\Product Affected				
	LT1B-FF Comcode 300386919				
15.	. Documentation Affected				
	Internal drawings and term sheets				
16.	Supplier Implementation Date	17. Modification Completi	on Date		
	6/15/07	6/15/07			
18.	Modification/Recall Location				
	None				
19.	Modification/Recall Cost				
	None				
20.	20. Location and Quantity of Equipment				
	N/A				
21.	1. Attachments				
	None				
22.	Comments				
	None				