



1. Supplier Information		2. Product Change/ Recall Notice No.	2a. Include on www.ofsoptics.com		
OFS, One BrightWave Boulevard, Carrollton, GA 30117 Contact: Diretress Sinkfield, Product Development Engineer (770)838-5302 Diretress.Sinkfield@ofsoptics.com		2008-0007-1 D	Yes		
3. Issue Date of Change/Recall	4. System & Product D	Description			
April 13, 2008	XpressTube Product	Code			
5. New Product ID	6. Old Product ID	6. Old Product ID			
<i>x</i> 56X - <i>nnn</i> - <i>yyy</i> - z	x56X - nnn- y	УУУ			
Where:	Where:				
• x is the fiber type	• x is the fiber ty				
• nnn is the number of fibers	• nnn is the numb				
• yyy is the fiber maximum attenuation	• yyy is the fiber	maximum attenuation			
• z is the jacket color					
7. Associated Products or Changes Affe XpressTube Cables	cted				
8. Drawing No.	9. Product Change Cla	ssification			
087-01	Class D				
10. Classification Substantiation	1				
Minor improvement.					
11. Reason(s) for Change/Recall					
To identify the cable's outer jacket cold	To identify the cable's outer jacket color.				
12. Description of Change/Recall	12. Description of Change/Recall				
Character and the end of product code will identify the jacket color.					
13. Effect of Change/Recall					
No change in form, fit or function.					
14. Material/Product Affected					
All XpressTube cables.					
15. Documentation Affected					
Only internal documents will be affected					
16. Supplier Implementation Date	17. Modification Com	pletion Date			
April 17, 2008	April 21, 2008				
18. Modification/Recall Location					
N/A					
19. Modification/Recall Cost					
No additional cost.					
20. Location and Quantity of Equipment					
N/A					





2.1	Attachments	
-1.	Auacimicina	,

N/A

22. Comments

Customers may receive cables without the jacket color in the old product code after this date until old inventory is consumed.