



A Furukawa Company

Product Change Notice/
Product Recall Notice

| | | | |
|--|---|---|---|
| 1. Supplier Information OFS, One BrightWave Boulevard, Carrollton, GA 30117 Contact: Diretress Sinkfield, Product Development Engineer (770)838-5302 Diretress.Sinkfield@ofsoptics.com | | 2. Product Change/ Recall Notice No. 2008-0008-1 B | 2a. Include on www.ofsoptics.com Yes |
| 3. Issue Date of Change/Recall 04/21/2008 | 4. System & Product Description Ripcord addition to the following cables: <ul style="list-style-type: none"> • ACCUMAX[®] (LGBC) cables with fiber counts ≥18 • Minicord[®] Breakout (LGMC) cables with fiber counts ≥18 • AccuDry[®] (LGIO) cables with fiber counts ≥18 • AccuFlex[™] Plus Round Ribbon Cables (all fiber counts) | | |
| 5. New Product ID N/A | 6. Old Product ID N/A | | |
| 7. Associated Products or Changes Affected <ul style="list-style-type: none"> • ACCUMAX (LGBC), Minicord Breakout (LGMC), AccuDry (LGIO) cables with fiber counts ≥18 • AccuFlex Plus Round Ribbon Cables | | | |
| 8. Drawing No. 221-PR-XXX & 221-PH-XXX | 9. Product Change Classification Class B | | |
| 10. Classification Substantiation Major improvement. | | | |
| 11. Reason(s) for Change/Recall To have the ability to rip the jacket for easy access to the fibers. | | | |
| 12. Description of Change/Recall An orange ripcord will be added under the sheath for the following cables: <ul style="list-style-type: none"> • ACCUMAX (LGBC), Minicord Breakout Cable (LGMC), AccuDry (LGIO) with fiber counts ≥18 • AccuFlex Plus Round Ribbon Cables This change will not affect the functionality of the cable in any way. | | | |
| 13. Effect of Change/Recall Product enhancement. No change in fit. Change in form to add ripcord. | | | |
| 14. Material/Product Affected <ul style="list-style-type: none"> • ACCUMAX Distribution Cable: Cables beginning with “LGBC-<i>nnn</i>” where <i>nnn</i> is the fiber count ≥18 • Minicord Breakout Cable: Cables beginning with “LGMC-<i>nnn</i>” where <i>nnn</i> is the fiber count ≥18 • AccuDry Indoor/Outdoor Cable: Cables beginning with “LGIO-<i>nnn</i> “ where <i>nnn</i> is the fiber count ≥18 • AccuFlex Plus Round Ribbon Cables. Cables beginning with “RRC-<i>nnn</i> “ where <i>nnn</i> is the fiber count | | | |
| 15. Documentation Affected <ul style="list-style-type: none"> • ACCUMAX (LGBC), Minicord Breakout Cable (LGMC), AccuDry (LGIO) and AccuFlex Plus data sheets • OFS internal manufacturing documents | | | |
| 16. Supplier Implementation Date 04/21/08. Customers may receive the cables identified without a ripcord under the jacket after this date until old inventory is consumed. | 17. Modification Completion Date 05/01/2008 | | |
| 18. Modification/Recall Location N/A | | | |



| |
|---|
| 19. Modification/Recall Cost N/A |
| 20. Location and Quantity of Equipment N/A |
| 21. Attachments N/A |
| 22. Comments Customers may receive the following cables without a ripcord under the jacket after this date until old inventory is consumed: <ul style="list-style-type: none">• ACCUMAX (LGBC) cables with fiber counts ≥ 18• Minicord Breakout (LGMC) cables with fiber counts ≥ 18• AccuDry (LGIO) cables with fiber counts ≥ 18• AccuFlex Plus Round Ribbon Cables (all fiber counts) |