



A Furukawa Company

Product Change Notice/
Product Recall Notice

1. Supplier Information OFS, One BrightWave Boulevard, Carrollton, GA 30117 Contact Engineer: Lynda Price (770) 798-3154 lmprice@ofsoptics.com		2. Product Change/ Recall Notice No. 2010-0007-1 D	2a. Include on www.ofsoptics.com Yes
3. Issue Date of Change/Recall March 15, 2010	4. System & Product Description Shielded Adapters		
5. New Product ID N/A	6. Old Product ID Attached		
7. Associated Products or Changes Affected Shielded Adapters.			
8. Drawing No. Multiple Drawings	9. Product Change Classification D		
10. Classification Substantiation Products are discontinued.			
11. Reason(s) for Change/Recall Plating Vendor went out of business			
12. Description of Change/Recall Discontinued Product Availability			
13. Effect of Change/Recall N/A			
14. Material/Product Affected Shielded Adapters			
15. Documentation Affected Discontinued Data Sheet			
16. Supplier Implementation Date 3/15/2010	17. Modification Completion Date 4/2/2010		
18. Modification/Recall Location N/A			
19. Modification/Recall Cost N/A			
20. Location and Quantity of Equipment N/A			
21. Attachments List of Codes (attached)			
22. Comments None			

Discontinued Codes	
109163659	C6000-RP-SA SC
109148288	C1101A-1-SA LC
300387966	C1101A-1-S LC
300387974	C1101A-1-S-100 LC
300387982	C1101A-2-S LC
300387990	C1101A-2-S-100 LC
108904368	C1101A-2-SA-1 LC (Long Dust Caps)
300432267	C1101A-2-SA-100 LC (Short Dust Caps)
300561552	C1101A-2-SAUM-1 LC (Long Dust Caps)
108904368	C1101A-2-SA-1 LC (Long Dust Caps)
300432267	C1101A-2-SA-100 LC (Short Dust Caps)
300561552	C1101A-2-SAUM-1 LC (Long Dust Caps)
109188649	C1104A-2-S LC
109188664	C1104A-2-S-100 LC
109188631	C1104A-2-SS LC
109188656	C1104A-2-SS-100 LC
300388402	C1204A-2-SS LC
300388410	C1204A-2-SS-100 LC
300517570	C1101A-2-S-1000
109999194	C1101A-2-SA-100 LC