



A Furukawa Company

Product Change Notice/  
Product Recall Notice

<b>1. Supplier Information</b> OFS, One BrightWave Boulevard, Carrollton, GA 30117 Contact Engineer: Lynda Price (770) 798-3154 <a href="mailto:lmprice@ofsoptics.com">lmprice@ofsoptics.com</a>		<b>2. Product Change/ Recall Notice No.</b>  <b>2012-0011-2 D</b>	<b>2a. Include on www.ofsoptics.com</b>  <b>Yes</b>
<b>3. Issue Date of Change/Recall</b> May 14, 2012	<b>4. System &amp; Product Description</b> Fiber Optic Riser Rated Patch Cords		
<b>5. New Product ID</b> N/A	<b>6. Old Product ID</b> List of Patch Cord Types Attached. Doesn't include every length and connector type		
<b>7. Associated Products or Changes Affected</b> Affects Riser Rated Patch Cords			
<b>8. Drawing No.</b> Multiple Drawings	<b>9. Product Change Classification</b> D		
<b>10. Classification Substantiation</b> The change doesn't impact form, fit or function. The change is the cordage used in the OFS Patch Cords where the internal Nylon buffer will change to a Low Smoke PVC buffer currently used in the Plenum Cordage. The print stream on the cordage will change to a 9P code from and LG code.			
<b>11. Reason(s) for Change/Recall</b> To replace the use of the Nylon buffer.			
<b>12. Description of Change/Recall</b> Internal buffer inside the cordage. This will not change the OD of the cordage itself.			
<b>13. Effect of Change/Recall</b> N/A			
<b>14. Material/Product Affected</b> List of codes follows.			
<b>15. Documentation Affected</b> Drawings changed.			
<b>16. Supplier Implementation Date</b> Transition starting 5/14/2012	<b>17. Modification Completion Date</b> Dependent on the amount of inventory of the various cordage types		
<b>18. Modification/Recall Location</b> N/A			
<b>19. Modification/Recall Cost</b> N/A			
<b>20. Location and Quantity of Equipment</b> N/A			
<b>21. Attachments</b> List of Codes			
<b>22. Comments</b> None			



A Furukawa Company

Product Change Notice/  
Product Recall Notice

**Product List:**

BW1	JR1ZA001	JR3ZA001	ML4
DMX-MW2	JR1ZA002	JR3ZA002	MM1
DMX-MW4	JR1ZA004	LAM-MW2	MM2
DMX-MW8	JR2FA001	LAM-MW8	MM4
DMX-MW12	JR2FA002	LAM-MW12	MW1
JR1BB001	JR2LO001	LAM-MW24	MW2
JR1BB002	JR2LO002	LAM-MW48	MW4
JR1FA001	JR2LO004	LF1	MW4
JR1FA002	JR2MO001	LF2	MZ1
JR1FA004	JR2MO002	LL1	MZ2
JR1LO001	JR2WY001	LL2	MZ4
JR1LO002	JR2WY002	LM1	WF1
JR1LO004	JR2ZA001	LM2	WF2
JR1MO001	JR2ZA002	LW1	WL1
JR1MO002	JR3FA001	LW2	WL2
JR1MO004	JR3FA002	LZ1	WL4
JR1WB001	JR3LO001	LZ2	WM1
JR1WB002	JR3LO002	MF1	WM2
JR1WV004	JR3MO001	MF2	WW1
JR1WY001	JR3MO002	MF4	WW2
JR1WY002	JR3WY001	ML1	WZ1
JR1WY004	JR3WY002	ML2	WZ2