



1. Supplier Information OFS, 2000 Northeast Expwy, Norcross, GA 30071 Contact Engineer: Dan Hendrickson: 770-798-5971 dahendrickson@ofsoptics.com Hongo Zhang: 770-798-4282 hzhang12@ofsoptics.com		2. Product Change/Recall Notice No. <p style="text-align: center;">2006-0004-1 B</p>
3. Issue Date of Change/Recall 11/22/2005	4. System & Product Description LGX LT1B Splice Tray Cover Color Change	
5. New Product ID LT1B-F/F LT1B-MF/MF LT1B-M/M No change to order codes or descriptors	6. Old Product ID	
7. Associated Products or Changes Affected All Combination Units and splice trays using LT1B configurations		
8. Drawing No. a05ak1091-0001	9. Product Change Classification Class B	
10. Classification Substantiation		
11. Reason(s) for Change/Recall Entry covers changed from clear plastic to CO white to match the entire tray assembly		
12. Description of Change/Recall Entry covers changed from clear plastic to CO white to match the entire tray assembly		
13. Effect of Change/Recall No impact on product usage		
14. Material/Product Affected No affect to material. Color chips added.		
15. Documentation Affected Not applicable		
16. Supplier Implementation Date 11/25/2005	17. Modification Completion Date N/A	
18. Modification/Recall Location Not Applicable		
19. Modification/Recall Cost Not Applicable		
20. Location and Quantity of Equipment Not Applicable		
21. Attachments None		
22. Comments This product change does not impact the fit, form or function of the current LT1B series splice tray system.		