



A Furukawa Company

Product Change Notice/
Product Recall Notice

1. Supplier Information OFS, One BrightWave Boulevard, Carrollton, GA 30117 Contact Engineer: Eric Joyce (770) 838-5054 etjoyce@ofsoptics.com		2. Product Change/ Recall Notice No. 2010-0012-1 D	2a. Include on www.ofsoptics.com Yes
3. Issue Date of Change/Recall August 11, 2010	4. System & Product Description 20" x 8" x 12" Plywood Cordage Reels		
5. New Product ID N/A	6. Old Product ID N/A		
7. Associated Products or Changes Affected All 20" (flange) x 8" (Traverse) x12 (Hub)" plywood cordage reels.			
8. Drawing No. N/A	9. Product Change Classification D		
10. Classification Substantiation			
11. Reason(s) for Change/Recall To standardize on reels for Premises products. All plywood reels used on Premises cordage and riser products will have a 1.5" arbor hole.			
12. Description of Change/Recall <ul style="list-style-type: none"> Arbor hole diameter for 20" x 8" x 12" plywood cordage reel changed from 1.75" to 1.5" Flanges changed from plywood to medium density fiberboard (MDF). A MDF reel flange will have better dimensional stability and will be "flatter" than a typical plywood flange. 			
13. Effect of Change/Recall None. Do not change fit or function.			
14. Material/Product Affected <ul style="list-style-type: none"> All cordages that ship on 20"(Flange) x 8"(Traverse) x 12"(Hub) cordage reels. Change will take affect once the in-process inventory is used. Cables on 20x8x12" reels in inventory or in process may have the 1.75" arbor hole and plywood flanges. 			
15. Documentation Affected Not applicable.			
16. Supplier Implementation Date August 11, 2010	17. Modification Completion Date September 1, 2010 or before		
18. Modification/Recall Location N/A			
19. Modification/Recall Cost N/A			
20. Location and Quantity of Equipment N/A			
21. Attachments N/A			
22. Comments See Figure 1			

Figure 1:

