



A Furukawa Company

Product Change Notice/
Product Recall Notice

1. Supplier Information OFS FITEL LLC, One BrightWave Boulevard, Carrollton, GA 30117 Contact Engineer: Lawrence Lavelanet llavelanet@ofsoptics.com		2. Product Change/ Recall Notice No. 2011-0002-1 D	2a. Include on www.ofsoptics.com Yes
3. Issue Date of Change/Recall 02/01/2011	4. System & Product Description Repair Services of discontinued fusion splicers and cleavers.		
5. New Product ID n/a	6. Old Product ID n/a		
7. Associated Products or Changes Affected S174, S175, S321, S218A			
8. Drawing No. n/a	9. Product Change Classification Class D		
10. Classification Substantiation n/a			
11. Reason(s) for Change/Recall Replacement parts no longer available to complete services and repairs			
12. Description of Change/Recall Repair services for the S174 and S175 Fusion splicers, the S321 Cleaver and the S218A Thermal Stripper are discontinued as of February 1, 2011.			
13. Effect of Change/Recall N/A			
14. Material/Product Affected S174, S175, S321, S218A			
15. Documentation Affected None			
16. Supplier Implementation Date 2/1/2011	17. Modification Completion Date 2/28/2011		
18. Modification/Recall Location N/A			
19. Modification/Recall Cost N/A			
20. Location and Quantity of Equipment N/A			
21. Attachments None			
22. Comments Customer requests for repairs on these products will be honored on a case by case basis until June 1, 2011; only as parts are available.			