



A Furukawa Company

Product Change Notice/
Product Recall Notice

1. Supplier Information OFS One BrightWave Boulevard, Carrollton, GA 30117 Contact Engineer: Leruth Bell (770) 798-4342 lbell@ofsoptics.com		2. Product Change/ Recall Notice No. 2012-0008-1 B	2a. Include on www.ofsoptics.com Yes
3. Issue Date of Change/Recall March 19, 2012	4. System & Product Description AccuPack™ Cordages		
5. New Product ID <i>Example: APBC-nnnC-xHy</i> Where: <i>nnn</i> is the fiber counts (002 – 012) <i>x</i> is the fiber type <i>y</i> is the jacket color	6. Old Product ID <i>Example: APBC-nnnB-xHy</i> Where: <i>nnn</i> is the fiber counts (002 – 012) <i>x</i> is the fiber type <i>y</i> is the jacket color		
7. Associated Products or Changes Affected AccuPack™ Cordages 2-12 fiber			
8. Drawing No. N/A	9. Product Change Classification B		
10. Classification Substantiation To move the create an alternate jacket material source for the low smoke zero halogen (LSZH) material used in AccuPack™ Cords			
11. Reason(s) for Change/Recall New jacket material is more readily available and easier to process. The former jacket material is being replaced because of availability and processing. Alternate material sources found that create a no form, fit, or function change to the product.			
12. Description of Change/Recall Current LSZH materials replaced with a substitute LSZH material supplier.			
13. Effect of Change/Recall No change in form, fit or function.			
14. Material/Product Affected Cables in inventory or already in process may contain version “B” in the cable print and may contain the old jacket material. Therefore, customers may receive cables with “B” in the cable print and the old jacket material until old inventory is consumed. Cables manufactured after 4/15/2012 will be jacketed with the alternate LSZH material.			
15. Documentation Affected AccuPack™ Cable Data sheets			
16. Supplier Implementation Date June 1, 2012	17. Modification Completion Date June 30, 2012		
18. Modification/Recall Location N/A			
19. Modification/Recall Cost N/A			
20. Location and Quantity of Equipment N/A			
21. Attachments N/A			



A Furukawa Company

Product Change Notice/
Product Recall Notice

22. Comments

1. ECO# 12-C-005 was issued for internal notification. Refer to Table 1 for affected products.
2. Samples are available upon request.
3. Qualification reports are available upon request.

Table 1

Part Number	Old Product Code	New Product Code
PR0-000-775	APBC-002B-DHW	APBC-002C-DHW
PR1-000-781	APBC-002B-DHW-RLX-500M	APBC-002C-DHW-RLX-500M
PR0-000-511	APBC-004B-DHW	APBC-004C-DHW
PR1-000-329	APBC-004B-DHW-RLX-200M	APBC-004C-DHW-RLX-200M
PR1-000-333	APBC-004B-WHG-BT	APBC-004C-WHG-BT
PR0-000-529	APBC-004B-WHY	APBC-004C-WHY
PR0-000-630	APBC-006B-DHW	APBC-006C-DHW
PR1-000-436	APBC-008B-WHB-BT	APBC-008C-WHB-BT
PR1-000-236	APBC-008B-WHG-BT	APBC-008C-WHG-BT
PR1-000-240	APBC-008B-WHR-BT	APBC-008C-WHR-BT
PR1-000-242	APBC-008B-WHS-BT	APBC-008C-WHS-BT
PR1-000-241	APBC-008B-WHV-BT	APBC-008C-WHV-BT
PR0-000-530	APBC-008B-WHY	APBC-008C-WHY
PR0-000-624	APBC-012B-DHW	APBC-012C-DHW
PR0-000-590	APBC-012B-WHG	APBC-012C-WHG
PR1-000-437	APBC-012B-WHG-BT	APBC-012C-WHG-BT
PR1-000-271	APBC-012B-WHO-BT	APBC-012C-WHO-BT
PR0-000-531	APBC-012B-WHY	APBC-012C-WHY
PR0-000-730	APBC-012B-YHW	APBC-012C-YHW
PR0-000-434	APIO-002B-DHK	APIO-002C-DHK
PR1-000-256	APIO-002B-DHK-RLX-500M	APIO-002C-DHK-RLX-500M
PR0-000-757	APIO-002B-DHW	APIO-002C-DHW
PR0-000-439	APIO-002B-WHK	APIO-002C-WHK
PR1-000-249	APIO-002B-WHK-RLX-500M	APIO-002C-WHK-RLX-500M
PR0-000-435	APIO-004B-DHK	APIO-004C-DHK
PR1-000-536	APIO-004B-DHK	APIO-004C-DHK
PR1-000-257	APIO-004B-DHK-RLX-500M	APIO-004C-DHK-RLX-500M
PR0-000-510	APIO-004B-DHW	APIO-004C-DHW
PR0-000-440	APIO-004B-WHK	APIO-004C-WHK
PR1-000-250	APIO-004B-WHK-RLX-500M	APIO-004C-WHK-RLX-500M
PR0-000-436	APIO-006B-DHK	APIO-006C-DHK
PR1-000-258	APIO-006B-DHK-RLX-500M	APIO-006C-DHK-RLX-500M
PR0-000-441	APIO-006B-WHK	APIO-006C-WHK
PR1-000-251	APIO-006B-WHK-RLX-500M	APIO-006C-WHK-RLX-500M
PR0-000-437	APIO-008B-DHK	APIO-008C-DHK

Table 1

Part Number	Old Product Code	New Product Code
PR1-000-247	APIO-008B-DHK-RLX-500M	APIO-008C-DHK-RLX-500M
PR0-000-442	APIO-008B-WHK	APIO-008C-WHK
PR1-000-252	APIO-008B-WHK-RLX-500M	APIO-008C-WHK-RLX-500M
PR0-000-438	APIO-012B-DHK	APIO-012C-DHK
PR1-000-248	APIO-012B-DHK-RLX-500M	APIO-012C-DHK-RLX-500M
PR0-000-924	APIO-012B-LHK	APIO-012C-LHK
PR0-000-443	APIO-012B-WHK	APIO-012C-WHK
PR1-000-253	APIO-012B-WHK-RLX-500M	APIO-012C-WHK-RLX-500M