



A Furukawa Company

Product Change Notice/
Product Recall Notice

1. Supplier Information OFS, 10 BrightWave Boulevard, Carrollton, GA 30117 Contact Product Engineer: x Imprice@ofsoptics.com		2. Product Change/ Recall Notice No. 2012-0015-1 D	2a. Include on www.ofsoptics.com Yes
3. Issue Date of Change/Recall 7/5/2012	4. System & Product Description ST™ II + (STP) Single-Mode and Multimode Connectors, Jumpers and PreConnectorized Cables with up-jacketing		
5. New Product ID ST2 in product description	6. Old Product ID STP in product description		
7. Associated Products or Changes Affected All single-mode and multimode connector kits, jumpers and Pre-Connectorized Cables utilizing the ST II +. The boot color for the single-mode ST II connector.			
8. Drawing No. A08AK1058; A08AK1091	9. Product Change Classification D		
10. Classification Substantiation This is a discontinued availability notice. Due to the decline in the ST business OFS is consolidating the product offering and moving all of the volume from the ST II + to the standard ST Connector. The boot color on the ST II when used on a jumper will change from yellow to blue for the single-mode code.			
11. Reason(s) for Change/Recall Decline in ST Connector usage			
12. Description of Change/Recall Changing from offering both the ST II + and the (standard) ST II to offering the (standard) ST II.			
13. Effect of Change/Recall No effect as the ST II will be substituted for the ST II +			
14. Material/Product Affected Existing codes of connectors, jumpers and Pre-Connectorized Cables coded STP.			
15. Documentation Affected Data sheets.			
16. Supplier Implementation Date Transition 7/20/2012 until material depleted	17. Modification Completion Date Upon transition of inventory		
18. Modification/Recall Location N/A			
19. Modification/Recall Cost N/A			
20. Location and Quantity of Equipment N/A			
21. Attachments List of Connector Kits and examples of jumper and Pre-Connectorized Cable codes.			
22. Comments None			



A Furukawa Company

Product Change Notice/
Product Recall Notice

Discontinued Availability Notice and Substitution:

Discontinued Code		Replacement Code	
Comcode	Product Code	Comcode	Product Code
107082786	P2070A-Z-125	106812274	P2020C-Z-125
300439783	P2070A-Z-125-100	106952500	P2020C-Z-125-100
300467222	P2070A-Z-125-1000	108327438	P2020C-Z-125-1000
108327412	P2070A-Z-125 (1000 PK)		
107226714	P2071A-Z-125-100		
301015020	P2072A-Z-125-100 2mm		
108918558	P2080A-Z-100 2.4		
107082810	P3070A-Z-125	106812258	P3020A-Z-125
107227076	P3070A-Z-125-100	106952518	P3020A-Z-125-100
300464732	P3070A-Z-125-1000	109000836	P3020A-Z-125-1000

Example of Jumper Change:

JR2WY001STPSTP003M

JR2WY001STUSTU003M

Example of Preconnectorized Cable:

LPC2-W-SCUSTP-BR09-048-0100F-39UJ

LPC2-W-SCUSTU-BR09-048-0100F-39UJ