



A Furukawa Company

**Product Change Notice/
Product Recall Notice**

1. Supplier Information OFS 10 BrightWave Boulevard, Carrollton, GA 30117 Contact Engineer: Dan Hendrickson (770)798-5971 dahendrickson@ofsoptics.com		2. Product Change/ Recall Notice No. 2013-0013-1 B	2a. Include on www.ofsoptics.com Yes
3. Issue Date of Change/Recall October 18, 2013	4. System & Product Description Add an alternative ribbon matrix material to increase supply base of UV curable materials that provide an equivalent behaving material while increase supply base.		
5. New Product ID Not applicable. No Changes to the external product	6. Old Product ID Not applicable. No Changes to the external product		
7. Associated Products or Changes Affected This is a Class B change per Telcorida GR-209 Revision 6 definitions. Specific customer notifications will occur per Signed / valid contractual obligations. AccuFlex [®] + Cables (ARRC) and Flat Ribbon Cords (FLRC)			
8. Drawing No. N/A	9. Product Change Classification B		
10. Classification Substantiation This is a Class B change per Telcorida GR-209 Revision 6 definitions. Addition of alternative UV curable matrix materials for ribbons.			
11. Reason(s) for Change/Recall Improve performance and ease of matrix removal.			
12. Description of Change/Recall Alternate matrix material.			
13. Effect of Change/Recall No change in fit, form or function.			
14. Material/Product Affected All ribbon cables sourced from Carrollton, GA USA			
15. Documentation Affected N/A			
16. Supplier Implementation Date November 15, 2013	17. Modification Completion Date November 15, 2013		
18. Modification/Recall Location N/A			
19. Modification/Recall Cost N/A			
20. Location and Quantity of Equipment N/A			
21. Attachments None			
22. Comments Refer to Tables A & B for list of products that will be revised by November 15, 2013			



A Furukawa Company

Product Change Notice/
Product Recall Notice

Table A – AccuFlex® + Cables

Part Number	Descriptor	Part Number	Descriptor
PR0-000-247-0270	ARRC-012A-ADY-9	PR0-000-864-0269	ARRC-048A-WDB-4
PR0-000-836-2312	ARRC-012A-FDA-G	PR0-000-236-0269	ARRC-048A-WDY-4
PR0-000-495-2306	ARRC-012A-MDO-G	PR0-000-243-0270	ARRC-048F-APY-9
PR0-000-861-0269	ARRC-012A-WDB-4	PR1-000-232-0270	ARRC-048F-APY-9
PR0-001-200-0269	ARRC-012A-WDY-4	PR0-000-540-0270	ARRC-048F-APY-9
PR1-000-191-0270	ARRC-012F-APY-9	PR0-000-736-0270	ARRC-048F-APY-9
PR0-000-482-0270	ARRC-012F-APY-9	PR0-000-740-0269	ARRC-048F-WPY-4
PR0-000-570-0270	ARRC-012F-APY-9	PR1-000-044-0269	ARRC-060A-WDY-4-MPO
PR0-000-483-2312	ARRC-012F-FPA-G	PR0-000-237-0270	ARRC-072A-ADY-9
PR0-000-499-2306	ARRC-012F-MPO-G	PR0-000-840-2312	ARRC-072A-FDA-G
PR0-000-484-2308	ARRC-012F-ZPA-G	PR0-000-488-2306	ARRC-072A-MDO-G
PR0-000-249-0270	ARRC-024A-ADY-9	PR0-000-865-0269	ARRC-072A-WDB-4
PR0-000-837-2312	ARRC-024A-FDA-G	PR0-000-419-0269	ARRC-072A-WDY-4
PR0-000-250-0269	ARRC-024A-WDY-4	PR0-001-212-0270	ARRC-072F-APY-4
PR1-000-519-8841	ARRC-024F-3PA-G	PR1-000-190-0270	ARRC-072F-APY-9
PR0-000-747-0270	ARRC-024F-APY-9	PR0-001-193-0269	ARRC-072F-WPW-4
PR0-000-175-0270	ARRC-024F-APY-9	PR0-000-907-0269	ARRC-072F-WPY-4
PR0-000-541-2252	ARRC-024F-LPO-U	PR0-000-234-0270	ARRC-096A-ADY-9
PR0-000-542-2306	ARRC-024F-MPO-G	PR0-000-841-2312	ARRC-096A-FDA-G
PR0-001-210-0269	ARRC-024F-WPW-4	PR0-000-290-2252	ARRC-096A-LDO-U
PR0-000-276-0270	ARRC-036A-ADY-9	PR0-000-289-2252	ARRC-096A-LDS-U
PR0-000-838-2312	ARRC-036A-FDA-G	PR0-000-866-0269	ARRC-096A-WDB-4
PR0-000-321-2252	ARRC-036A-LDO-U	PR0-000-534-0269	ARRC-096A-WDY-4
PR0-000-863-0269	ARRC-036A-WDB-4	PR0-000-476-0270	ARRC-144A-ADY-9
PR0-000-277-0269	ARRC-036A-WDY-4	PR0-000-842-2312	ARRC-144A-FDA-G
PR0-000-233-0270	ARRC-048A-ADY-9	PR0-000-867-0269	ARRC-144A-WDB-4
PR0-000-364-2312	ARRC-048A-FDA-G	PR0-000-477-0269	ARRC-144A-WDY-4

Table B – AccuRibbon® Cordage

Part Number	Descriptor	Part Number	Descriptor
PR0-000-573-2312	FLRC-012B-FHA-G	PR1-000-097-2306	FLRC-012A-MPO-G-FAA
PR0-000-496-2306	FLRC-008B-MHO-G	PR0-000-597-0269	FLRC-004B-WPY-4
PR0-000-481-2306	FLRC-012B-MHO-G	PR0-000-598-0269	FLRC-006B-WPY-4
PR0-000-513-0269	FLRC-006B-WHV-4	PR0-000-599-0269	FLRC-008B-WPY-4
PR0-000-593-0269	FLRC-008B-WHB-4	PR0-000-391-0269	FLRC-012B-WPY-4
PR1-000-837-0269	FLRC-008A-WHY-4-MPO	PR0-000-516-2308	FLRC-012B-ZPA-G
PR1-000-906-0269	FLRC-008A-WHY-4-MPO-1420D	PR0-000-631-0270	FLRC-008A-ARY-9
PR0-000-373-0269	FLRC-012B-WHY-4	PR0-000-571-0270	FLRC-012A-ARY-9
PR0-000-293-2308	FLRC-012B-ZHA-G	PR0-000-928-2252	FLRC-012A-LRO-U
PR0-000-674-8841	FLRC-012B-3PA-G	PR0-000-562-2306	FLRC-012A-MRO-G
PR0-000-424-0270	FLRC-006B-APY-9	PR0-000-588-0269	FLRC-004A-WRY-4
PR0-000-376-0270	FLRC-008B-APY-9	PR0-000-312-0269	FLRC-006A-WRY-4
PR0-000-245-0270	FLRC-012B-APY-9	PR0-000-601-0269	FLRC-008A-WRY-4
PR0-000-292-2252	FLRC-006B-LPO-U	PR0-000-313-0269	FLRC-012A-WRY-4



A Furukawa Company

Product Change Notice/
Product Recall Notice

Table B – AccuRibbon® Cordage			
Part Number	Descriptor	Part Number	Descriptor
PR0-000-320-2252	FLRC-008B-LPO-U	PR0-000-683-2308	FLRC-012A-ZRA-G
PR0-000-515-2252	FLRC-012B-LPO-U	PR1-000-028-0269	FLRC-008B-WPA-4
PR1-000-409-2252	FLRC-012A-LPO-U-FAA	PR1-000-027-0269	FLRC-008B-WPO-4
PR0-000-381-2306	FLRC-008B-MPO-G	PR1-000-183-0262	FLRC-008B-WHB-4-MPO
PR0-000-311-2306	FLRC-012B-MPO-G		