



A Furukawa Company

Product Change Notice/  
Product Recall Notice

<b>1. Supplier Information</b> OFS 10 BrightWave Boulevard, Carrollton, GA 30117 Contact: Dan Hendrickson (770)798-5971 <a href="mailto:dahendrickson@ofsoptics.com">dahendrickson@ofsoptics.com</a>		<b>2. Product Change/ Recall Notice No.</b>  <b>2016-0008-1 MD</b>	<b>2a. Include on www.ofsoptics.com</b>  <b>YES</b>
<b>3. Issue Date of Change/Recall</b> January 20, 2016		<b>4. System &amp; Product Description</b> SBJ 900 μm fiber unit Manufacture Discontinued (MD)	
<b>5. New Product ID</b> <ul style="list-style-type: none"> <li>N/A Product Discontinued Availability</li> </ul>		<b>6. Old Product ID</b> <b>SBJ-001A- X<sub>2</sub> R X<sub>4</sub>- X<sub>5</sub></b> <b>SB09-001A- X<sub>2</sub> P X<sub>4</sub>- X<sub>5</sub></b>  ABREV- <i>nnn</i> V – X <sub>2</sub> X <sub>3</sub> X <sub>4</sub> - X <sub>5</sub> - X <sub>6</sub>  <b>Where:</b> <ul style="list-style-type: none"> <li>ABREV:             <ul style="list-style-type: none"> <li>SBJ or SB09</li> </ul> </li> <li><i>nnn</i> Fiber Count (001)</li> <li>V version A and B</li> <li>X<sub>2</sub> Fiber Type</li> <li>X<sub>3</sub> Jacket Rating</li> <li>X<sub>4</sub> Color</li> <li>X<sub>5</sub> Fiber Attenuation</li> <li>X<sub>6</sub> Special Notations</li> </ul>	
<b>7. Associated Products or Changes Affected</b> The SBJ 900 μm loose fiber construction will be discontinued. Customers seeking an ultra small OD cordage should consider the use of OFS' 1.2 mm M-Pack Cord.			
<b>8. Drawing No.</b> NA		<b>9. Product Change Classification</b> MD	
<b>10. Classification Substantiation</b> N/A			
<b>11. Reason(s) for Change/Recall</b> Lack of sales			
<b>12. Description of Change/Recall</b> N/A			
<b>13. Effect of Change/Recall</b> N/A			
<b>14. Material/Product Affected</b> <b>SBJ-001A- X<sub>2</sub> R X<sub>4</sub>- X<sub>5</sub></b> <b>SB09-001A- X<sub>2</sub> P X<sub>4</sub>- X<sub>5</sub></b>			
<b>15. Documentation Affected</b> N/A			
<b>16. Supplier Implementation Date</b> September 9, 2016		<b>17. Modification Completion Date</b> September 9, 2016	
<b>18. Modification/Recall Location</b> N/A			
<b>19. Modification/Recall Cost</b> N/A			
<b>20. Location and Quantity of Equipment</b> N/A			
<b>21. Attachments</b> N/A			
<b>22. Comments</b> N/A			

Table 1 Product Code Discontinued

Material	Material Description
700210842	5403 001A MRSL (SBJ-001A-LRS)
760004564	5403 001A WRYL (SBJ-001A-ARY)
300437241	SBJ-001A-ARY
PRO-000-592	SBJ-001A-ARY
PR1-000-711	SBJ-001A-DPW
108460452	SBJ-001A-LRS
PRO-000-228	SBJ-001A-LRS
PRO-000-843	SBJ-001A-MRO
PRO-000-528	SBJ-001A-WRW
300541737	SBJ-001A-WRY
PRO-000-062	SBJ-001A-WRY
PRO-000-062-0269	SB09-001B-WPY-4